

TECHNICAL BULLETIN – TB234

MAINTENANCE RECOMMENDATIONS FOR ARDEX WPM310 MEMBRANE APPLIED TO MASONRY WALLS.

Date, Tuesday 15 July 2014.

INTRODUCTION & SCOPE

The purpose of this bulletin is to outline the procedures recommended by Ardex Australia Pty. Ltd. For the maintenance of the Ardex WPM310 waterproofing membrane system used on exposed wall areas .

ABOUT THE SYSTEM.

Ardex WPM310 is a premium acrylic waterproofing membrane specifically designed for waterproofing exposed wall areas. Ardex WPM310 is an ultraviolet stable acrylic coating designed to provide long term exterior durability. The membrane may be recoated when necessary. In addition, the coating has the ability of self cleaning.

REGULAR MAINTENANCE

Regular maintenance consists of frequent inspection of all surfaces to ensure that they have not been damaged or penetrated.

INCIDENT REPAIR PROCEDURE

Incident damage should be repaired as quickly as possible following the incident to avoid subsequent consequential damage.

Thoroughly grind the damaged area(s) and feather the peripheral edges into the firmly bonded undamaged coating system. Apply one light coat of Ardex WPM270 solvent primer to all prepared/exposed surfaces and allow the primer to dry.

Reinstate the Ardex WPM310 coating over the prepared/exposed surfaces and extend the repair to overlap the existing coating by at least 50mm.

ROUTINE PERIODIC MAINTENANCE

All surfaces should be inspected periodically (suggested as 6 monthly) to identify areas of damage, such as cracking, gouging or rips.

The surface colour should be assessed to ensure there is no shadowing or show through evidence as a result of erosion of the coating.

For mechanically damaged areas, thoroughly grind the damaged area(s) and feather the peripheral edges into firmly bonded undamaged coating system. Apply one light coat of Ardex WPM 270 solvent primer to all prepared/exposed surfaces and allow it to dry.

Reinstate the Ardex WPM 310 membrane over the prepared/exposed surfaces and extend the repair to over lap the existing membrane by at least 50mm.

MAJOR MAINTENANCE

Major maintenance is recommended every 10 years. All surfaces should be washed down with high pressure water using a rotary head (turbo) nozzle at 14 MPa (2000 psi) pressure to remove any loose or poorly bonded coating. Refer to above "routine periodic maintenance" for re coating.

Do not use solvent based paints or cleaning agents that may damage the integrity of the coating.



IMPORTANT

This Technical Bulletin provides guideline information only and is not intended to be interpreted as a general specification for the application/installation of the products described. Since each project potentially differs in exposure/condition specific recommendations may vary from the information contained herein. For recommendations for specific applications/installations contact your nearest Ardex Australia or Ardex New Zealand Office.

DISCLAIMER

The information presented in this Technical Bulletin is to the best of our knowledge true and accurate. No warranty is implied or given as to its completeness or accuracy in describing the performance or suitability of a product for a particular application. Users are asked to check that the literature in their possession is the latest issue.

REASON FOR REVISION - ISSUER

New bulletin

DOCUMENT REVIEW REQUIRED

24 months from issue

Technical Services 1800 224 070. email: technicalservices@ardexaustralia.com

Australia <http://www.ardexaustralia.com>

NSW-HO 61 2 9851 9100, **QLD** 07 3817 6000, **VIC** 03 8339 3100, **SANT** 08 8406 2500, **WA** 08 9256 8600

Customer Service and Sales 1300 788 780

New Zealand Christ Church 64 3384 3029, Auckland 9636 0005, Wellington 4568 5949

Technical Inquiries NZ 0800 2 ARDEX New Zealand <http://www.ardex.co.nz>

Web: Corporate: <http://www.ardex.com>

